

PERMIT TO OPERATE AN AIR CONTAMINANT SOURCEDate of Issuance **11/23/90**Application No. **1734000066F002**Effective Date **11/23/90**Permit Fee **\$250**

This document constitutes issuance to:

**HARRISON MINING CORP.
44961 OLD HOPEDALE ROAD
CADIZ****OHIO 43907**

of a permit to operate for:

**COAL STORAGE PILE
PLANT'S COAL STORAGE PILE**

The following terms and conditions are hereby expressly incorporated into this permit to operate:

1. This permit to operate shall be effective until **11/23/93**
You will be contacted approximately six months prior to this date regarding the renewal of this permit. If you are not contacted, please write to the appropriate Ohio EPA field office.
2. The above-described source is and shall remain in full compliance with all applicable State and federal laws and regulations and the terms and conditions of this permit.
3. Prior to any modification of this source, as defined in rule 3745-31-01 of the Ohio Administrative Code (OAC), a permit to install must be granted by the Ohio EPA pursuant to OAC Chapter 3745-31.
4. The Director of the Ohio EPA or an authorized representative may, subject to the safety requirements of the permit holder, enter upon the premises of this source at any reasonable time for purposes of making inspections, conducting tests, examining records or reports pertaining to any emission of air contaminants, and determining compliance with any applicable State and federal air pollution laws and regulations and the terms and conditions of this permit.
5. A permit fee in the amount specified above must be remitted within 15 days from the issuance date of this permit.
6. Any transferee of this permit shall assume the responsibilities of the prior permit holder. The appropriate Ohio EPA field office must be notified in writing of any transfer of this permit.
7. This source and any associated air pollution control system(s) shall be maintained regularly in accordance with good engineering practices in order to minimize air contaminant emissions. Any malfunction of this source or any associated air pollution control system(s) shall be reported immediately to the appropriate Ohio EPA field office in accordance with OAC rule 3745-15-06. Except as provided in that rule, any scheduled maintenance or malfunction necessitating the shutdown or bypassing of any air pollution control system(s) shall be accompanied by the shutdown of this source.
8. Any unauthorized or emergency release of an air contaminant from this source which, due to the toxic or hazardous nature of the material, may pose a threat to public health, or otherwise endanger the safety or welfare of the public, shall be reported immediately to the appropriate Ohio EPA field office (during normal business hours) or to the Ohio EPA's Emergency Response Group (1-800-282-9378). (Additional reporting may be required pursuant to the federal Comprehensive Environmental Response, Compensation, and Liability Act.)
9. The appropriate Ohio EPA field office is:
**NORTH OHIO VALLEY AIR AUTHORITY
514 ADAMS ST.
STUBENVILLE, OH 43952 (614) 282-3908/3303**
10. If this term and condition is checked, the permit holder is subject to the attached special terms and conditions.

OHIO ENVIRONMENTAL PROTECTION AGENCY

Director



APPLICAT ON NUMBER: 1734000066 F002
FACILITY NAME: Harrison Mining Corp.
EQUIPMENT DESCRIPTION: Coal Storage Pile
COMPANY ID: Plant's Coal Storage Pile

SPECIAL TERMS AND CONDITIONS

A. Source identification and applicable rules:

The operations covered by this Permit to Operate and the applicable particulate air pollution control regulations are:

1. Load In of Raw Coal - OAC Rule 3745-17-08
2. Wind Erosion - OAC Rule 3745-17-08
3. Load Out of Coal - OAC Rule 3745-17-08
4. Vehicle Traffic - OAC Rule 3745-17-08

B. Allowable particulate and fugitive dust emission limitations:

Harrison Mining Corp. shall comply with the applicable requirements of the Ohio Administrative Code and the applicable provisions herein as they relate to the fugitive dust emission source identified in paragraph A upon the effective date of the Permit to Operate.

1. Load In of Raw Coal

In accordance with the requirements of paragraph B of OAC Rule 3745-17-08, Harrison Mining Corp. shall maintain and employ the covered belt line to the storage pile and if the coal is not sufficiently wet and is emitting fugitive dust, water or any chemical dust suppressant shall be applied on an needed frequency in order to minimize or eliminate fugitive dust.

2. Wind Erosion

In accordance with the requirements of paragraph B of OAC Rule 3745-17-08, Harrison Mining Corp. shall maintain and operate the adjustable height stacker in such a manner as to minimize and eliminate fugitive dust.

3. Load Out of Coal

In accordance with the requirements of paragraph B of OAC Rule 3745-17-08, Harrison Mining Corp. shall use water or any chemical dust suppressant during load out operations when the coal is not sufficiently wet and is emitting fugitive dust.

4. Vehicle Traffic

In accordance with the requirements of paragraph B of OAC Rule 3745-17-08, Harrison Mining Corp. shall treat dusty surfaces with an oil that has been demonstrated to be non-toxic and OEPA approved, or any chemical dust suppressant in order to minimize or eliminate fugitive dust.