



John R. Kasich, Governor
Mary Taylor, Lt. Governor
Scott J. Nally, Director

10/15/2013

Certified Mail

Marcie Moore
Oxford Mining Co. Strasburg Wash Plant
40580 Cadiz Piedmont Rd
Cadiz, OH 43907

No	TOXIC REVIEW
No	SYNTHETIC MINOR TO AVOID MAJOR NSR
No	CEMS
No	MACT/GACT
No	NSPS
No	NESHAPS
No	NETTING
No	MODELING SUBMITTED
No	SYNTHETIC MINOR TO AVOID TITLE V
No	FEDERALLY ENFORCABLE PTIO (FEPTIO)
No	SYNTHETIC MINOR TO AVOID MAJOR GHG

RE: FINALAIR POLLUTION PERMIT-TO-INSTALL AND OPERATE

Facility ID: 0679000017
Permit Number: P0113830
Permit Type: Renewal
County: Tuscarawas

Dear Permit Holder:

Enclosed please find a final Ohio Environmental Protection Agency (EPA) Air Pollution Permit-to-Install and Operate (PTIO) which will allow you to install, modify, and/or operate the described emissions unit(s) in the manner indicated in the permit. Because this permit contains conditions and restrictions, please read it very carefully. In this letter you will find the information on the following topics:

- **How to appeal this permit**
- **How to save money, reduce pollution and reduce energy consumption**
- **How to give us feedback on your permitting experience**
- **How to get an electronic copy of your permit**

How to appeal this permit

The issuance of this PTIO is a final action of the Director and may be appealed to the Environmental Review Appeals Commission pursuant to Section 3745.04 of the Ohio Revised Code. The appeal must be in writing and set forth the action complained of and the grounds upon which the appeal is based. The appeal must be filed with the Commission within thirty (30) days after notice of the Director's action. The appeal must be accompanied by a filing fee of \$70.00, made payable to "Ohio Treasurer Josh Mandel," which the Commission, in its discretion, may reduce if by affidavit you demonstrate that payment of the full amount of the fee would cause extreme hardship. Notice of the filing of the appeal shall be filed with the Director within three (3) days of filing with the Commission. Ohio EPA requests that a copy of the appeal be served upon the Ohio Attorney General's Office, Environmental Enforcement Section. An appeal may be filed with the Environmental Review Appeals Commission at the following address:

Environmental Review Appeals Commission
77 South High Street, 17th Floor
Columbus, OH 43215

How to save money, reduce pollution and reduce energy consumption

The Ohio EPA is encouraging companies to investigate pollution prevention and energy conservation. Not only will this reduce pollution and energy consumption, but it can also save you money. If you would like to learn ways you can save money while protecting the environment, please contact our Office of Compliance Assistance and Pollution Prevention at (614) 644-3469. Additionally, all or a portion of the capital expenditures related to installing air pollution control equipment under this permit may be eligible for financing and State tax exemptions through the Ohio Air Quality Development Authority (OAQDA) under Ohio Revised Code Section 3706. For more information, see the OAQDA website: www.ohioairquality.org/clean_air

How to give us feedback on your permitting experience

Please complete a survey at www.epa.ohio.gov/survey.aspx and give us feedback on your permitting experience. We value your opinion.

How to get an electronic copy of your permit

This permit can be accessed electronically via the eBusiness Center: Air Services in Microsoft Word format or in Adobe PDF on the Division of Air Pollution Control (DAPC) Web page, www.epa.ohio.gov/dapc by clicking the "Search for Permits" link under the Permitting topic on the Programs tab.

If you have any questions, please contact Ohio EPA DAPC, Southeast District Office at (740)385-8501 or the Office of Compliance Assistance and Pollution Prevention at (614) 644-3469.

Sincerely,



Michael W. Ahern, Manager

Permit Issuance and Data Management Section, DAPC

Cc: Ohio EPA-SEDO



FINAL

**Division of Air Pollution Control
Permit-to-Install and Operate
for
Oxford Mining Co. Strasburg Wash Plant**

Facility ID:	0679000017
Permit Number:	P0113830
Permit Type:	Renewal
Issued:	10/15/2013
Effective:	10/15/2013
Expiration:	9/30/2023



Division of Air Pollution Control
Permit-to-Install and Operate
for
Oxford Mining Co. Strasburg Wash Plant

Table of Contents

Authorization	1
A. Standard Terms and Conditions	3
1. What does this permit-to-install and operate ("PTIO") allow me to do?.....	4
2. Who is responsible for complying with this permit?	4
3. What records must I keep under this permit?	4
4. What are my permit fees and when do I pay them?.....	4
5. When does my PTIO expire, and when do I need to submit my renewal application?	4
6. What happens to this permit if my project is delayed or I do not install or modify my source?	5
7. What reports must I submit under this permit?	5
8. If I am required to obtain a Title V operating permit in the future, what happens to the operating provisions and PER obligations under this permit?	5
9. What are my obligations when I perform scheduled maintenance on air pollution control equipment? ...	5
10. Do I have to report malfunctions of emissions units or air pollution control equipment? If so, how must I report?	6
11. Can Ohio EPA or my local air agency inspect the facility where the emission unit(s) is/are located?	6
12. What happens if one or more emissions units operated under this permit is/are shut down permanently?	6
13. Can I transfer this permit to a new owner or operator?.....	7
14. Does compliance with this permit constitute compliance with OAC rule 3745-15-07, "air pollution nuisance"?	7
15. What happens if a portion of this permit is determined to be invalid?	7
B. Facility-Wide Terms and Conditions.....	8
C. Emissions Unit Terms and Conditions	10
1. F002, Coal Preparation and Processing.....	11



Final Permit-to-Install and Operate
Oxford Mining Co. Strasburg Wash Plant
Permit Number: P0113830
Facility ID: 0679000017
Effective Date: 10/15/2013

Authorization

Facility ID: 0679000017
Application Number(s): A0047410, A0047412
Permit Number: P0113830
Permit Description: PTIO Renewal permit for coal processing including unloading, crushing, transfer, conveying and load-out
Permit Type: Renewal
Permit Fee: \$0.00
Issue Date: 10/15/2013
Effective Date: 10/15/2013
Expiration Date: 9/30/2023
Permit Evaluation Report (PER) Annual Date: Jan 1 - Dec 31, Due Feb 15

This document constitutes issuance to:

Oxford Mining Co. Strasburg Wash Plant
7551 Reed Rd. NW
Strasburg, OH 44680

of a Permit-to-Install and Operate for the emissions unit(s) identified on the following page.


Ohio Environmental Protection Agency (EPA) District Office or local air agency responsible for processing and administering your permit:

Ohio EPA DAPC, Southeast District Office
2195 Front Street
Logan, OH 43138
(740)385-8501

The above named entity is hereby granted this Permit-to-Install and Operate for the air contaminant source(s) (emissions unit(s)) listed in this section pursuant to Chapter 3745-31 of the Ohio Administrative Code. Issuance of this permit does not constitute expressed or implied approval or agreement that, if constructed or modified in accordance with the plans included in the application, the described emissions unit(s) will operate in compliance with applicable State and federal laws and regulations.

This permit is granted subject to the conditions attached hereto.

Ohio Environmental Protection Agency


Scott J. Nally
Director



Final Permit-to-Install and Operate
Oxford Mining Co. Strasburg Wash Plant
Permit Number: P0113830
Facility ID: 0679000017
Effective Date: 10/15/2013

Authorization (continued)

Permit Number: P0113830
Permit Description: PTIO Renewal permit for coal processing including unloading, crushing, transfer, conveying and load-out

Permits for the following Emissions Unit(s) or groups of Emissions Units are in this document as indicated below:

Emissions Unit ID:	F002
Company Equipment ID:	Coal Crushing and Material Handling
Superseded Permit Number:	06-1350
General Permit Category and Type:	Not Applicable



Final Permit-to-Install and Operate
Oxford Mining Co. Strasburg Wash Plant
Permit Number: P0113830
Facility ID: 0679000017
Effective Date: 10/15/2013

A. Standard Terms and Conditions



1. What does this permit-to-install and operate ("PTIO") allow me to do?

This permit allows you to install and operate the emissions unit(s) identified in this PTIO. You must install and operate the unit(s) in accordance with the application you submitted and all the terms and conditions contained in this PTIO, including emission limits and those terms that ensure compliance with the emission limits (for example, operating, recordkeeping and monitoring requirements).

2. Who is responsible for complying with this permit?

The person identified on the "Authorization" page, above, is responsible for complying with this permit until the permit is revoked, terminated, or transferred. "Person" means a person, firm, corporation, association, or partnership. The words "you," "your," or "permittee" refer to the "person" identified on the "Authorization" page above.

The permit applies only to the emissions unit(s) identified in the permit. If you install or modify any other equipment that requires an air permit, you must apply for an additional PTIO(s) for these sources.

3. What records must I keep under this permit?

You must keep all records required by this permit, including monitoring data, test results, strip-chart recordings, calibration data, maintenance records, and any other record required by this permit for five years from the date the record was created. You can keep these records electronically, provided they can be made available to Ohio EPA during an inspection at the facility. Failure to make requested records available to Ohio EPA upon request is a violation of this permit requirement.

4. What are my permit fees and when do I pay them?

There are two fees associated with permitted air contaminant sources in Ohio:

- PTIO fee. This one-time fee is based on a fee schedule in accordance with Ohio Revised Code (ORC) section 3745.11, or based on a time and materials charge for permit application review and permit processing if required by the Director.

You will be sent an invoice for this fee after you receive this PTIO and payment is due within 30 days of the invoice date. You are required to pay the fee for this PTIO even if you do not install or modify your operations as authorized by this permit.

- Annual emissions fee. Ohio EPA will assess a separate fee based on the total annual emissions from your facility. You self-report your emissions in accordance with Ohio Administrative Code (OAC) Chapter 3745-78. This fee assessed is based on a fee schedule in ORC section 3745.11 and funds Ohio EPA's permit compliance oversight activities. Unless otherwise specified, facilities subject to one or more synthetic minor restrictions must use Ohio EPA's "Air Services" to submit annual emissions associated with this permit requirement. Ohio EPA will notify you when it is time to report your emissions and to pay your annual emission fees.

5. When does my PTIO expire, and when do I need to submit my renewal application?

This permit expires on the date identified at the beginning of this permit document (see "Authorization" page above) and you must submit a renewal application to renew the permit. Ohio EPA will send a renewal notice to you approximately six months prior to the expiration date of this permit. However, it is



very important that you submit a complete renewal permit application (postmarked prior to expiration of this permit) even if you do not receive the renewal notice.

If a complete renewal application is submitted before the expiration date, Ohio EPA considers this a timely application for purposes of ORC section 119.06, and you are authorized to continue operating the emissions unit(s) covered by this permit beyond the expiration date of this permit until final action is taken by Ohio EPA on the renewal application.

6. What happens to this permit if my project is delayed or I do not install or modify my source?

This PTIO expires 18 months after the issue date identified on the "Authorization" page above unless otherwise specified if you have not (1) started constructing the new or modified emission sources identified in this permit, or (2) entered into a binding contract to undertake such construction. This deadline can be extended by up to 12 months, provided you apply to Ohio EPA for this extension within a reasonable time before the 18-month period has ended and you can show good cause for any such extension.

7. What reports must I submit under this permit?

An annual permit evaluation report (PER) is required in addition to any malfunction reporting required by OAC rule 3745-15-06 or other specific rule-based reporting requirement identified in this permit. Your PER due date is identified in the Authorization section of this permit.

8. If I am required to obtain a Title V operating permit in the future, what happens to the operating provisions and PER obligations under this permit?

If you are required to obtain a Title V permit under OAC Chapter 3745-77 in the future, the permit-to-operate portion of this permit will be superseded by the issued Title V permit. From the effective date of the Title V permit forward, this PTIO will effectively become a PTI (permit-to-install) in accordance with OAC rule 3745-31-02(B). The following terms and conditions will no longer be applicable after issuance of the Title V permit: Section B, Term 1.b) and Section C, for each emissions unit, Term a)(2).

The PER requirements in this permit remain effective until the date the Title V permit is issued and is effective, and cease to apply after the effective date of the Title V permit. The final PER obligation will cover operations up to the effective date of the Title V permit and must be submitted on or before the submission deadline identified in this permit on the last day prior to the effective date of the Title V permit.

9. What are my obligations when I perform scheduled maintenance on air pollution control equipment?

You must perform scheduled maintenance of air pollution control equipment in accordance with OAC rule 3745-15-06(A). If scheduled maintenance requires shutting down or bypassing any air pollution control equipment, you must also shut down the emissions unit(s) served by the air pollution control equipment during maintenance, unless the conditions of OAC rule 3745-15-06(A)(3) are met. Any emissions that exceed permitted amount(s) under this permit (unless specifically exempted by rule) must be reported as deviations in the annual permit evaluation report (PER), including nonexempt excess emissions that occur during approved scheduled maintenance.



10. Do I have to report malfunctions of emissions units or air pollution control equipment? If so, how must I report?

If you have a reportable malfunction of any emissions unit(s) or any associated air pollution control system, you must report this to the Ohio EPA DAPC, Southeast District Office in accordance with OAC rule 3745-15-06(B). Malfunctions that must be reported are those that result in emissions that exceed permitted emission levels. It is your responsibility to evaluate control equipment breakdowns and operational upsets to determine if a reportable malfunction has occurred.

If you have a malfunction, but determine that it is not a reportable malfunction under OAC rule 3745-15-06(B), it is recommended that you maintain records associated with control equipment breakdown or process upsets. Although it is not a requirement of this permit, Ohio EPA recommends that you maintain records for non-reportable malfunctions.

11. Can Ohio EPA or my local air agency inspect the facility where the emission unit(s) is/are located?

Yes. Under Ohio law, the Director or his authorized representative may inspect the facility, conduct tests, examine records or reports to determine compliance with air pollution laws and regulations and the terms and conditions of this permit. You must provide, within a reasonable time, any information Ohio EPA requests either verbally or in writing.

12. What happens if one or more emissions units operated under this permit is/are shut down permanently?

Ohio EPA can terminate the permit terms associated with any permanently shut down emissions unit. "Shut down" means the emissions unit has been physically removed from service or has been altered in such a way that it can no longer operate without a subsequent "modification" or "installation" as defined in OAC Chapter 3745-31.

You should notify Ohio EPA of any emissions unit that is permanently shut down by submitting¹ a certification that identifies the date on which the emissions unit was permanently shut down. The certification must be submitted by an authorized official from the facility. You cannot continue to operate an emissions unit once the certification has been submitted to Ohio EPA by the authorized official.

You must comply with all recordkeeping and reporting for any permanently shut down emissions unit in accordance with the provisions of the permit, regulations or laws that were enforceable during the period of operation, such as the requirement to submit a PER, air fee emission report, or malfunction report. You must also keep all records relating to any permanently shutdown emissions unit, generated while the emissions unit was in operation, for at least five years from the date the record was generated.

Again, you cannot resume operation of any emissions unit certified by the authorized official as being permanently shut down without first applying for and obtaining a permit pursuant to OAC Chapter 3745-31.

¹ Permittees that use Ohio EPA's "Air Services" can mark the affected emissions unit(s) as "permanently shutdown" in the facility profile along with the date the emissions unit(s) was permanently removed and/or disabled. Submitting the facility profile update will constitute notifying of the permanent shutdown of the affected emissions unit(s).



13. Can I transfer this permit to a new owner or operator?

You can transfer this permit to a new owner or operator. If you transfer the permit, you must follow the procedures in OAC Chapter 3745-31, including notifying Ohio EPA or the local air agency of the change in ownership or operator. Any transferee of this permit must assume the responsibilities of the transferor permit holder.

14. Does compliance with this permit constitute compliance with OAC rule 3745-15-07, "air pollution nuisance"?

This permit and OAC rule 3745-15-07 prohibit operation of the air contaminant source(s) regulated under this permit in a manner that causes a nuisance. Ohio EPA can require additional controls or modification of the requirements of this permit through enforcement orders or judicial enforcement action if, upon investigation, Ohio EPA determines existing operations are causing a nuisance.

15. What happens if a portion of this permit is determined to be invalid?

If a portion of this permit is determined to be invalid, the remainder of the terms and conditions remain valid and enforceable. The exception is where the enforceability of terms and conditions are dependent on the term or condition that was declared invalid.



Final Permit-to-Install and Operate
Oxford Mining Co. Strasburg Wash Plant
Permit Number: P0113830
Facility ID: 0679000017
Effective Date: 10/15/2013

B. Facility-Wide Terms and Conditions



1. This permit document constitutes a permit-to-install issued in accordance with ORC 3704.03(F) and a permit-to-operate issued in accordance with ORC 3704.03(G).
 - a) For the purpose of a permit-to-install document, the facility-wide terms and conditions identified below are federally enforceable with the exception of those listed below which are enforceable under state law only.
 - (1) None.
 - b) For the purpose of a permit-to-operate document, the facility-wide terms and conditions identified below are enforceable under state law only with the exception of those listed below which are federally enforceable.
 - (1) None.
2. The following emission unit contained in this permit is subject to 40 CFR Part 60, Subpart Y: F002. The complete NSPS requirements may be accessed via the internet from the Electronic Code of Federal Regulations (e-CFR) website <http://ecfr.gpoaccess.gov> or by contacting the appropriate Ohio EPA District Office or local air agency.



Final Permit-to-Install and Operate
Oxford Mining Co. Strasburg Wash Plant
Permit Number: P0113830
Facility ID: 0679000017
Effective Date: 10/15/2013

C. Emissions Unit Terms and Conditions



1. F002, Coal Preparation and Processing

Operations, Property and/or Equipment Description:

150 ton per hour coal preparation and processing including hopper load-in, crushing, washing, and conveyor transfers installed in 1976; supersedes PTI 06-224 issued October 4, 1976, for EU P001, PTI 06-1350 issued July 20, 1988, for EU F002, and PTI 06-2225 issued December 30, 1992, for EU F006

a) This permit document constitutes a permit-to-install issued in accordance with ORC 3704.03(F) and a permit-to-operate issued in accordance with ORC 3704.03(G).

(1) For the purpose of a permit-to-install document, the emissions unit terms and conditions identified below are federally enforceable with the exception of those listed below which are enforceable under state law only.

a. None.

(2) For the purpose of a permit-to-operate document, the emissions unit terms and conditions identified below are enforceable under state law only with the exception of those listed below which are federally enforceable.

a. None.

b) Applicable Emissions Limitations and/or Control Requirements

(1) The specific operation(s), property, and/or equipment that constitute each emissions unit along with the applicable rules and/or requirements and with the applicable emissions limitations and/or control measures are identified below. Emissions from each unit shall not exceed the listed limitations, and the listed control measures shall be specified in narrative form following the table.

	Applicable Rules/Requirements	Applicable Emissions Limitations/Control Measures
a.	OAC rule 3745-31-05(A)(3) (As established in PTI 06-2225 issued December 30, 1992)	Fugitive particulate emissions (PE) shall not exceed 2.97 tons per year (TPY). Visible fugitive PE shall not exceed 20% opacity as a three-minute average. Best available control measures that are sufficient to minimize or eliminate visible emissions of fugitive dust. See b)(2)b. through b)(2)d. below.
b.	OAC rule 3745-17-08(B)	See b)(2)e. below.
c.	OAC rule 3745-17-07(B)	See b)(2)f. below.
d.	40 CFR Part 60, Subpart Y (40 CFR 60.250 – 60.258)	The requirements specified in 40 CFR 60.254(a) are less stringent than the requirements established pursuant to



	Applicable Rules/Requirements	Applicable Emissions Limitations/Control Measures
	[In accordance with 40 CFR 60.250(b), this emissions unit includes coal processing and conveying equipment and coal transfer and loading systems that commenced construction, reconstruction or modification after October 27, 1974 and on or before April 28, 2008, processing more than 200 tons of coal per day, subject to the emissions limitations specified in this section.]	OAC rule 3745-31-05(A)(3). See b)(2)g. below.
e.	40 CFR 60.1-19 (40 CFR 60.1a)	The provisions of Subpart A apply to the owner or operator of any stationary source which contains an affected facility that commenced construction or modification after the date of publication in 40 CFR Part 60 that is applicable to that facility.

(2) Additional Terms and Conditions

- a. The material handling operations that are covered by this permit and subject to the above-mentioned requirements are listed below:

Feed hopper load-in
 Primary crushing
 Cleaning
 Material transfers

- b. The permittee shall employ best available control measures for the above-identified material handling operations for the purpose of ensuring compliance with the above-mentioned applicable requirements. In accordance with the permittee's permit application, the permittee has committed to perform the following control measures to ensure compliance:

<u>Material Handling Operation(s):</u>	<u>Control Measure(s):</u>
Feed hopper load-in	Maintain inherent moisture in coal and partial enclosures
Primary crushing	Maintain inherent moisture in coal and partial enclosures
Cleaning	Wet process inside building
Material transfers	Maintain inherent moisture in coal and partial enclosures



- c. For each material handling operation that is not adequately enclosed, the above-identified control measures shall be implemented if the permittee determines, as a result of the inspection conducted pursuant to the monitoring section of this permit, that the control measures are necessary to ensure compliance with the above-mentioned applicable requirements. Any required implementation of the control measures shall continue during the operation of the material handling operations until further observation confirms that use of the control measure(s) is unnecessary.
- d. Implementation of the above-mentioned control measures in accordance with the terms and conditions of this permit is appropriate and sufficient to satisfy the requirements of OAC rule 3745-31-05.
- e. This facility is located in Tuscarawas County, which is not an "Appendix A" area as indicated in Appendix A of OAC rule 3745-17-08. Therefore, pursuant to OAC rule 3745-17-08(A)(1), it is exempt from the requirements of OAC rule 3745-17-08.
- f. This emissions unit is exempt from the visible particulate emission limitation in OAC rule 3745-17-07(B) pursuant to OAC rule 3745-17-07(B)(7).
- g. Compliance with 40 CFR Part 60 Subpart Y is required within 60 days after achieving the maximum production rate at which the affected facility will be operated, but not later than 180 days after initial startup of such facility, pursuant to 40 CFR 60.245(a) and 60.8.

c) Operational Restrictions

- (1) None.

d) Monitoring and/or Recordkeeping Requirements

- (1) Except as otherwise provided in this section, for material handling operations that are not adequately enclosed, the permittee shall perform inspections of such operations in accordance with the following minimum frequencies:

Material Handling Operation(s): Minimum Inspection Frequency:

All

Daily

- (2) The above-mentioned inspections shall be performed during representative, normal operating conditions.
- (3) The permittee may, upon receipt of written approval from the appropriate Ohio EPA District Office or local air agency, modify the above-mentioned inspection frequencies if operating experience indicates that less frequent inspections would be sufficient to ensure compliance with the above-mentioned applicable requirements.
- (4) The permittee shall maintain records of the following information:
 - a. The date and reason any required inspection was not performed;



- b. The date of each inspection where it was determined by the permittee that it was necessary to implement the control measures;
- c. The dates the control measures were implemented; and
- d. On a calendar quarter basis, the total number of days the control measures were implemented.

The information in (4)d. shall be kept separately for each material handling operation identified above, and shall be updated on a calendar quarter basis within 30 days after the end of each calendar quarter.

e) Reporting Requirements

- (1) The permittee shall submit an annual Permit Evaluation Report (PER) to the Ohio EPA District Office or Local Air Agency by the due date identified in the Authorization section of this permit. The permit evaluation report shall cover a reporting period of no more than twelve-months for each air contaminant source identified in this permit. It is recommended that the PER is submitted electronically through the Ohio EPA's "eBuisness Center: Air Services" although PERs can be submitted via U.S. postal service or can be hand delivered.
- (2) Unless documentation can be submitted to demonstrate that these requirements have been met, the permittee submit notifications and reports to the appropriate Ohio EPA district office as required pursuant to 40 CFR Part 60, Subparts A and Y for the following sections:

60.7(a)(1)	Notification of date of construction or reconstruction of an affected facility
60.7(a)(3)	Notification of the actual date of initial startup of an affected facility
60.7(a)(4)	Notification of any physical or operational change to an existing facility which may increase the emission rate of any air pollutant to which a standard applies, unless that change is specifically exempted under an applicable subpart or in §60.14(e).
60.7(a)(6)	Notification of the anticipated date for conducting the opacity observations required by §60.11(e)(1).



f) Testing Requirements

(1) Compliance with the Emissions Limitations and/or Control Requirements specified in section b) of these terms and conditions shall be determined in accordance with the following methods:

a. Emissions Limitation:

Fugitive PE shall not exceed 2.97TPY.

Applicable Compliance Method:

Plant Load-in

$$EF = [k(0.0032)[(U/5)^{1.3}/(M/2)^{1.4}] \quad (\text{AP-42 Section 13.2-4, 11/06})$$

Where:

EF = emission factor expressed in pounds per ton

k = particle size multiplier for TSP (dimensionless) = 0.74

U = mean wind speed expressed in miles per hour (MPH) = 9.7

M = material moisture content (%) = 8.0%

Therefore, EF = 0.000805lb PE/ton

$$[(EF)(\# \text{ of load-in points})(\text{Max Annual Tons Per Year Throughput})]/2,000 \text{ lbs/ton}$$

$$[(0.000805 \text{ lb PE/ton})(1)(1,314,000 \text{ TPY})]/2,000 \text{ lbs/ton}$$

$$= 0.53 \text{ TPY PE}$$

Control efficiency = 95%

Therefore, (0.53 TPY)(0.05)= 0.03 TPY PE

Crushing

$$[(EF)(\# \text{ of crushers})(\text{Max Annual Tons Per Year Throughput})]/2,000 \text{ lbs/ton}$$

Where EF = 0.0054 lb PE/ton (AP-42 Section 11.19.2, 8/04)

$$[(0.0054 \text{ lb PE/ton})(1)(1,314,000 \text{ TPY})]/2,000 \text{ lbs/ton}$$

$$= 3.55 \text{ TPY PE}$$

Control efficiency = 95%

Therefore, (3.55 TPY)(0.05)= 0.18 TPY PE



Conveyor Transfer Point

$[(EF)(\# \text{ of transfer points})(\text{Max Annual Tons Per Year Throughput})]/2,000 \text{ lbs/ton}$

Where $EF = 0.003 \text{ lb PE/ton}$ (AP-42 Section 11.19.2, 8/04)

$[(0.003 \text{ lb PE/ton})(14)(1,314,000 \text{ TPY})]/2,000 \text{ lbs/ton}$

= 27.60 controlled TPY PE

Control efficiency = 90%

Therefore, $(27.60 \text{ TPY})(0.10) = 2.76 \text{ TPY PE}$

Emissions Summary:

$(0.03 \text{ TPY}) + (0.18 \text{ TPY}) + (2.76 \text{ TPY}) = 2.97 \text{ TPY}$

b. Emissions Limitation:

Visible fugitive PE shall not exceed 20% opacity as a three-minute average.

Applicable Compliance Method:

If required, visible particulate emissions shall be determined according to USEPA Method 9

- (2) Unless documentation can be submitted to demonstrate that the requirement has been met, performance testing shall be conducted as required in 40 CFR Part 60 Subpart Y pursuant to 40 CFR 60.255. The permittee shall conduct, or have conducted, emission testing for this emissions unit in accordance with the following requirements:
- a. The emission testing shall be conducted within sixty (60) days after the effective date of this permit.
 - b. The emissions testing shall be conducted to demonstrate compliance with the visible PE limitations for fugitive emissions in accordance with the requirements of 40 CFR Part 60.255(a).
 - c. The following test method(s) shall be employed to demonstrate compliance with the allowable emission rate(s): for visible emissions, Method 9 of 40 CFR 60, Appendix A.
 - d. The test(s) shall be conducted while the emissions unit is operating at or near its maximum capacity, unless otherwise specified or approved by the Ohio EPA, Southeast District Office.
 - e. No later than thirty (30) days prior to the proposed test date(s), the permittee shall submit an "Intent to Test" notification to the Ohio EPA, Southeast District Office. The "Intent to Test" notification shall describe in detail the proposed test methods and procedures, the emissions unit operating parameters, the time(s)



and date(s) of the test(s), and the person(s) who will be conducting the test(s). Failure to submit such notification for review and approval prior to the test(s) may result in the Ohio EPA, Southeast District Office's refusal to accept the results of the emissions test(s).

- f. Personnel from the Ohio EPA, Southeast District Office shall be permitted to witness the test(s), examine the testing equipment, and acquire data and information necessary to ensure that the operation of the emissions unit and the testing procedures provide a valid characterization of the emissions from the emissions unit and/or the performance of the control equipment.
- g. A comprehensive written report on the results of the emissions test(s) shall be signed by the person or persons responsible for the tests and submitted to the Ohio EPA, Southeast District Office within 30 days following completion of test(s). The permittee may request additional time for the submittal of the written report, where warranted, with prior approval from the Ohio EPA, Southeast District Office.

g) Miscellaneous Requirements

- (1) None.