

# PERMIT TO OPERATE AN AIR CONTAMINANT SOURCE

Date of Issuance 11/09/89

Application No. 1734000056F001

Effective Date 11/09/89

Permit Fee \$250

This document constitutes issuance to:

YOUGHIOGHENY & OHIO COAL CO.  
GREEN TWSHP RD. 176  
GREEN TWSHP OHIO 43976


of a permit to operate for:

PETERS & KREBS COAL WASHING PLT. 500000 LBS/HR  
COAL CLEANING

The following terms and conditions are hereby expressly incorporated into this permit to operate:

1. This permit to operate shall be effective until 11/08/92.  
You will be contacted approximately six months prior to this date regarding the renewal of this permit. If you are not contacted, please write to the appropriate Ohio EPA field office.
2. The above-described source is and shall remain in full compliance with all applicable State and federal laws and regulations and the terms and conditions of this permit.
3. Prior to any modification of this source, as defined in rule 3745-31-01 of the Ohio Administrative Code (OAC), a permit to install must be granted by the Ohio EPA pursuant to OAC Chapter 3745-31.
4. The Director of the Ohio EPA or an authorized representative may, subject to the safety requirements of the permit holder, enter upon the premises of this source at any reasonable time for purposes of making inspections, conducting tests, examining records or reports pertaining to any emission of air contaminants, and determining compliance with any applicable State and federal air pollution laws and regulations and the terms and conditions of this permit.
5. A permit fee in the amount specified above must be remitted within 15 days from the issuance date of this permit.
6. Any transferee of this permit shall assume the responsibilities of the prior permit holder. The appropriate Ohio EPA field office must be notified in writing of any transfer of this permit.
7. This source and any associated air pollution control system(s) shall be maintained regularly in accordance with good engineering practices in order to minimize air contaminant emissions. Any malfunction of this source or any associated air pollution control system(s) shall be reported immediately to the appropriate Ohio EPA field office in accordance with OAC rule 3745-15-06. Except as provided in that rule, any scheduled maintenance or malfunction necessitating the shutdown or bypassing of any air pollution control system(s) shall be accompanied by the shutdown of this source.
8. Any unauthorized or emergency release of an air contaminant from this source which, due to the toxic or hazardous nature of the material, may pose a threat to public health, or otherwise endanger the safety or welfare of the public, shall be reported immediately to the appropriate Ohio EPA field office (during normal business hours) or to the Ohio EPA's Emergency Response Group (1-800-282-9378). (Additional reporting may be required pursuant to the federal Comprehensive Environmental Response, Compensation, and Liability Act.)
9. The appropriate Ohio EPA field office is:  
NORTH OHIO VALLEY AIR AUTHORITY  
814 ADAMS ST.  
STUEBENVILLE, OH 43952 (614) 282-3908/3303
10.  If this term and condition is checked, the permit holder is subject to the attached special terms and conditions.

OHIO ENVIRONMENTAL PROTECTION AGENCY



Director

APPLICAT ON NUMBER: 1734000056 F001  
FACILITY NAME: Youghiogheny & Ohio Coal Co., Nelms #2 Mine  
EQUIPMENT DESCRIPTION: Peters & Krebs Coal Washing Plt. 500,000 lbs/hr  
COMPANY ID: Coal Cleaning

### SPECIAL TERMS AND CONDITIONS

Source identification and applicable rules:

The operations covered by this Permit to Operate and the applicable particulate air pollution control regulations are:

1. Coal Cleaning - OAC Rule 3745-31-05

Allowable particulate and fugitive dust emission limitations:

Youghiogheny & Ohio Coal Co., Nelms #2 Mine, shall comply with the applicable requirements of the Ohio Administrative Code and the applicable provisions herein as they relate to the fugitive dust emission source identified in paragraph A upon the effective date of the Permit to Operate.

1. Coal Cleaning

In accordance with the requirements of paragraph B of OAC Rule 3745-31-05, Youghiogheny & Ohio Coal Co., Nelms #2 Mine, shall clean coal in a wet manner such that there are no visible emissions of particulate matter from the building's doors, windows and ventilators.

Youghiogheny & Ohio Coal Co., Nelms #2 Mine, shall comply with any applicable state and federal requirements concerning the disposal of waste material generated at this facility.

AC:kl

EPA 3164  
02/14/83

PREPARED BY: Al Carducci  
DATE PREPARED: September 26, 1989