

**PERMIT TO OPERATE AN AIR CONTAMINANT SOURCE**

Date of Issuance 03/15/91

Application No. 1741060204F002

Effective Date 03/15/91

Permit Fee \$100

This document constitutes issuance to:

BARNEY SNYDER OF OHIO, INC.  
FAIR & WATSON STREETS  
DILLONVALE

OHIO 43917

of a permit to operate for:

STORAGE PILES OF FERROUS & NON-FERROUS SCRAP  
YARD STORAGE PILES

The following terms and conditions are hereby expressly incorporated into this permit to operate:

1. This permit to operate shall be effective until 03/15/94  
You will be contacted approximately six months prior to this date regarding the renewal of this permit. If you are not contacted, please write to the appropriate Ohio EPA field office.
2. The above-described source is and shall remain in full compliance with all applicable State and federal laws and regulations and the terms and conditions of this permit.
3. Prior to any modification of this source, as defined in rule 3745-31-01 of the Ohio Administrative Code (OAC), a permit to install must be granted by the Ohio EPA pursuant to OAC Chapter 3745-31.
4. The Director of the Ohio EPA or an authorized representative may, subject to the safety requirements of the permit holder, enter upon the premises of this source at any time for purposes of making inspections, conducting tests, examining records or reports pertaining to any emission of air contaminants, and determining compliance with any applicable State and federal air pollution laws and regulations and the terms and conditions of this permit.
5. A permit fee in the amount specified above must be remitted within 15 days from the issuance date of this permit.
6. Any transferee of this permit shall assume the responsibilities of the prior permit holder. The appropriate Ohio EPA field office must be notified in writing of any transfer of this permit.
7. This source and any associated air pollution control system(s) shall be maintained regularly in accordance with good engineering practices in order to minimize air contaminant emissions. Any malfunction of this source or any associated air pollution control system(s) shall be reported immediately to the appropriate Ohio EPA field office in accordance with OAC rule 3745-15-06. Except as provided in that rule, any scheduled maintenance or malfunction necessitating the shutdown or bypassing of any air pollution control system(s) shall be accompanied by the shutdown of this source.
8. Any unauthorized or emergency release of an air contaminant from this source which, due to the toxic or hazardous nature of the material, may pose a threat to public health, or otherwise endanger the safety or welfare of the public, shall be reported immediately to the appropriate Ohio EPA field office (during normal business hours) or to the Ohio EPA's Emergency Response Group (1-800-282-9378). (Additional reporting may be required pursuant to the federal Comprehensive Environmental Response, Compensation, and Liability Act.)
9. The appropriate Ohio EPA field office is:  
NORTH OHIO VALLEY AIR AUTHORITY  
814 ADAMS ST.  
STEUBENVILLE, OH 43952 (614) 282-3908/3303
10.  If this term and condition is checked, the permit holder is subject to the attached special terms and conditions.

OHIO ENVIRONMENTAL PROTECTION AGENCY

*Berry Soannil*

Director

EPA 3834  
Revised 9-90

APPLICATION NUMBER: 1741060204 F002  
FACILITY NAME: Barney Snyder of Ohio, Inc.  
EQUIPMENT DESCRIPTION: Storage Piles of Ferrous and Non-ferrous Scrap  
COMPANY ID: Yard Storage Piles

### SPECIAL TERMS AND CONDITIONS

A. The following rules of the Ohio Administrative Code establish the applicable emission limitations and/or control requirements for this source.

1. Load In - OAC Rule 3745-17-08(B)
2. Wind Erosion - OAC Rule 3745-17-08(B)
3. Load Out - OAC Rule 3745-17-08(B)
4. Vehicle Traffic - OAC Rule 3745-17-08(B)

This condition in no way limits the applicability of other requirements of the Ohio Administrative Code.

B. Allowable Mass Emission Limitations and/or Control Requirements

1. Load In  
In accordance with the requirements of OAC Rule 3745-17-08(B), Barney Snyder of Ohio, Inc. shall apply a sufficient quantity of water when feasible to wet dusty material prior to load in activities in order to minimize and eliminate fugitive dust.
2. Wind Erosion  
In accordance with the requirements of OAC Rule 3745-17-08(B), Barney Snyder of Ohio, Inc. shall maintain and employ good operating practices and enclosures when possible to minimize and eliminate fugitive dust due to winds.
3. Load Out  
In accordance with the requirements of OAC Rule 3745-17-08(B), Barney Snyder of Ohio, Inc. shall apply a sufficient quantity of water to dusty material when loading out of piles in order to minimize or eliminate fugitive dust.
4. Vehicle Traffic  
In accordance with the requirements of OAC Rule 3745-17-08(B), Barney Snyder of Ohio, Inc. shall apply a sufficient quantity of water as needed to dusty surfaces at the storage area in order to minimize or eliminate fugitive dust caused by vehicular traffic associated with storage pile activities.