



State of Ohio Environmental Protection Agency

00 FEB 14 11  
O.E.P.A.  
S.E.D.O.

Street Address:

Lazarus Gov. Center  
122 S. Front Street  
Columbus, OH 43215

TELE: (614) 644-3020 FAX: (614) 644-2329

Mailing Address:

Lazarus Gov. Center  
P.O. Box 1049  
Columbus, OH 43216-1049

02/10/00

**CERTIFIED MAIL**

06-60-01-0010

Ballas Egg Products Corp.  
Craig Ballas  
40 North Second St.  
Zanesville, OH 43701

**RE: Final Chapter 3745-35 Permit To Operate**

Dear Craig Ballas:

The enclosed Permit(s) to Operate allow you to operate the described emissions unit(s) in the manner indicated in the Permit(s). Because each permit contains several terms and conditions, I urge you to read them carefully.

The Ohio EPA is urging companies to investigate pollution prevention and energy conservation. Not only will this reduce pollution and energy consumption, but it can also save you money. If you would like to learn ways you can save money while protecting the environment, please contact our Office of Pollution Prevention at (614) 644-3469.

You are hereby notified that this action of the Director is final and may be appealed to the Environmental Review Appeals Commission pursuant to Section 3745.04 of the Ohio Revised Code. The appeal must be in writing and set forth the action complained of and the grounds upon which the appeal is based. It must be filed with the Environmental Review Appeals Commission within thirty (30) days after notice of the Director's action. A copy of the appeal must be served on the Director of the Ohio Environmental Protection Agency within three (3) days of filing with the Commission. It is also requested by the Director that a copy of the appeal be served upon the Environmental Enforcement Section of the Office of the Attorney General. An appeal may be filed with the Environmental Review Appeals Commission at the following address:

Environmental Review Appeals Commission  
236 East Town Street  
Room 300  
Columbus, Ohio 43215

If you have any questions, please contact the Southeast District Office at (740) 385-8501.

Very truly yours,

Thomas G. Rigo, Manager  
Field Operations and Permit Section  
Division of Air Pollution Control

cc: Southeast District Office

## PERMIT TO OPERATE AN EMISSIONS UNIT

Effective Date: 02/10/00

Facility ID: 06-60-01-0010

Expiration Date: 02/10/05

**FINAL ISSUE**

This document constitutes issuance for:

Ballas Egg Products Corp.  
40 North Second St.  
Zanesville, OH 43701

of a permit to operate for:

P002 (Egg Shell Drying)  
Egg Shell Drying & Crushing System

### 1. Compliance Requirements

The above-described emissions unit is and shall remain in full compliance with all applicable State and federal laws and regulations and the terms and conditions of this permit.

### 2. Permit to Install Requirement

Prior to the "installation" or "modification" of any "air contaminant source," as those terms are defined in OAC rule 3745-31-01, a permit to install must be obtained from the Ohio EPA pursuant to OAC Chapter 3745-31.

### 3. Reporting Requirements Related to Monitoring and Recordkeeping Requirements

The permittee shall submit required reports in the following manner:

- a. Reports of any required monitoring and/or recordkeeping information shall be submitted to the appropriate Ohio EPA District Office or local air agency.
- b. Except as otherwise may be provided in the terms and conditions for a specific emissions unit, quarterly written reports of (a) any deviations (excursions) from emission limitations, operational restrictions, and control device operating parameter limitations that have been detected by the testing, monitoring, and recordkeeping requirements specified in this permit, (b) the probable cause of such deviations, and (c) any corrective actions or preventive measures which have been or will be taken, shall be submitted to the appropriate Ohio EPA District Office or local air agency. If no deviations occurred during a calendar quarter, the permittee shall submit a quarterly report, which states that no deviations occurred during that quarter. The reports shall be submitted quarterly, i.e., by January 31, April 30, July 31, and October 31 of each year and shall cover the previous calendar quarters. (These quarterly reports shall exclude deviations resulting from malfunctions reported in accordance with OAC rule 3745-15-06.)

#### **4. Records Retention Requirements**

Each record of any monitoring data, testing data, and support information required pursuant to this permit shall be retained for a period of five years from the date the record was created. Support information shall include, but not be limited to, all calibration and maintenance records and all original strip-chart recordings for continuous monitoring instrumentation, and copies of all reports required by the permit. Such records may be maintained in computerized form.

#### **5. Inspections and Information Requests**

The Director of the Ohio EPA, or an authorized representative of the Director, may, subject to the safety requirements of the permittee and without undue delay, enter upon the premises of this source at any reasonable time for purposes of making inspections, conducting tests, examining records or reports pertaining to any emission of air contaminants, and determining compliance with any applicable State and federal air pollution laws and regulations and the terms and conditions of this permit. The permittee shall furnish to the Director of the Ohio EPA, or an authorized representative of the Director, upon receipt of a written request and within a reasonable time, any information that may be requested to determine whether cause exists for modifying, reopening or revoking this permit or to determine compliance with this permit. Upon verbal or written request, the permittee shall also furnish to the Director of the Ohio EPA, or an authorized representative of the Director, copies of records required to be kept by this permit.

#### **6. Scheduled Maintenance/Malfunction Reporting**

Any scheduled maintenance of air pollution control equipment shall be performed in accordance with paragraph (A) of OAC rule 3745-15-06. The malfunction of any emissions unit or any associated air pollution control system(s) shall be reported to the appropriate Ohio EPA District Office or local air agency in accordance with paragraph (B) of OAC rule 3745-15-06. Except as provided in that rule, any scheduled maintenance or malfunction necessitating the shutdown or bypassing of any air pollution control system(s) shall be accompanied by the shutdown of this emissions unit(s) that is (are) served by such control system(s).

#### **7. Permit Transfers**

Any transferee of this permit shall assume the responsibilities of the prior permittee. The appropriate Ohio EPA District Office or local air agency must be notified in writing of any transfer of this permit.

#### **8. Air Pollution Nuisance**

The air contaminants emitted by the emissions units covered by this permit shall not cause a public nuisance, in violation of OAC rule 3745-15-07.

#### **9. Permit Renewal**

Approximately six months prior to the expiration date of this permit, a notice regarding the renewal of this permit should be sent to the permittee's designated facility contact. If you are not contacted, please contact the appropriate Ohio EPA District Office or local air agency. It is the permittee's responsibility to renew this permit even if no notice of its expiration is received.


10. The permittee is also subject to the attached special terms and conditions.

The following Ohio EPA District Office or local air agency has jurisdiction in the area in which the facility is located:

Southeast District Office  
2195 Front Street  
Logan, OH 43138  
(740) 385-8501

You will be contacted approximately six months prior to expiration date regarding the renewal of this permit. If you are not contacted, please contact the Southeast District Office.

OHIO ENVIRONMENTAL PROTECTION AGENCY

  
\_\_\_\_\_  
Christopher Jones  
Director

**Part II: Special Terms and Conditions**

**A. Applicable Emissions Limitations and/or Control Requirements**

1. The specific operation(s), property, and/or equipment which constitute this emissions unit are listed in the following table along with the applicable rules and/or requirements and with the applicable emissions limitations and/or control measures. Emissions from this unit shall not exceed the listed limitations, and the listed control measures shall be employed. Additional applicable emissions limitations and/or control measures (if any) may be specified in narrative form following the table.

<u>Operations, Property, and/or Equipment</u>	<u>Applicable Rules/ Requirements</u>	<u>Applicable Emissions Limitations/Control Measures</u>
Eggshell Drying and Crushing System vented to a fabric filter(P002)	OAC rule 3745-31-05	Emissions of particulate matter shall not exceed 0.030 grain per dry standard cubic foot of exhaust gases or there shall be no visible particulate emissions, whichever is less stringent. Particulate emissions shall not exceed 0.8 pounds per hour.
	OAC rule 3745-17-11	Less stringent than the above listed limit.
	OAC rule 3745-17-07	Less stringent than the above listed limit.

**2. Additional Terms and Conditions**

- 2.a All trucks shall be vented back to the dust collector during loadout to prevent fugitive emissions.

**B. Operational Restrictions**

None

**C. Monitoring and/or Record Keeping Requirements**

1. The permittee shall perform daily checks for any visible particulate emissions from the exhaust of the fabric filter control system. The presence or absence of any visible emissions from the exhaust of the fabric filter control system shall be noted in an operations log. If any visible emissions are observed, corrective actions shall be taken to eliminate the visible emissions and these actions shall also be noted in the operations log.

**D. Reporting Requirements**

1. The permittee shall submit deviation (excursion) reports that identify all days during which visible particulate emissions are observed from the exhaust of the fabric filter control system.

The reports shall be submitted on:

- a. January 31 of each year and shall cover the period from July 1 until December 31; and
- b. July 31 of each year and shall cover the period from January 1 until June 30.

If no visible particulate emissions are observed from the exhaust of the fabric filter control system during a given period, the permittee shall submit a report which states that no visible particulate emissions were observed from the exhaust of the fabric filter control system during that period. (These reports shall exclude deviations resulting from malfunctions reported in accordance with OAC rule 3745-15-06.)

**E. Testing Requirements**

1. Compliance with the particulate matter emission limits of 0.030 grain per dry standard cubic foot of exhaust gases and 0.8 pounds per hour shall be determined based on emission testing conducted in accordance with OAC rule 3745-17-03. Emission testing is not specifically required to demonstrate compliance with this emission limitation, but, if appropriate, may be requested pursuant to OAC rule 3745-15-04(A).

**E. Testing Requirements (continued)**

2. Compliance with the no visible emission limit for the exhaust from the dust collector shall be determined using Test Method 22-like visible emission observations. (Although Test Method 22 applies to fugitive emissions units, the visible/no visible emissions observation technique of Test Method 22 can be applied to ducted emissions, i.e., Test Method 22-like visible emission observations.)

**F. Miscellaneous Requirements**

None